

Midsouth Home Inspections
1280 River Hollow Cove
Cordova, TN 38016
(901) 336-3551
midsouthhomeinspections.com
diley123@yahoo.com
Inspected By: Dan Iley



Home Inspection Report

Prepared For:

Unspecified Client

Property Address:

4225

Arrowhead

Memphis, Tn 38118

Inspected on Thu, Mar 12 2026 at 8:38AM

Table of Contents

General	4
Site	4
Exterior	5
Roofing	7
Structure	8
Electrical	10
HVAC	15
Plumbing	17
Bathrooms	18
Kitchen	20
Laundry	22
Interior	22
Report Summary	27

Thank you for the opportunity to conduct a home inspection of the property listed above. We understand that the function of this report is to assist you in understanding the condition of the property to assist in making an informed purchase decision.

The report contains a review of components in the following basic categories: site, exterior, roofing, structure, electrical, HVAC, plumbing, and interior. Additional categories may or may not be included. The report is designed to be easy to read and comprehend however it is important to read the entire report to obtain a full understanding of the scope, limitations and exclusions of the inspection.

In addition to the checklist items of the report there are several comments which are meant to help you further understand certain conditions observed. These are easy to find by looking for their icons along the left side margin. Comments with the blue icon are primarily informational and comments with the orange icon are also displayed on the summary. Please read them all.

DEFINITION OF CONDITION TERMS

Satisfactory: At the time of inspection the component is functional without observed signs of a substantial defect.

Marginal: At the time of inspection the component is functioning but is estimated to be nearing end of useful life. Operational maintenance recommended. Replacement anticipated.

Repair or Replace: At the time of inspection the component does not function as intended or presents a Safety Hazard. Repair or replacement is recommended.

Further Evaluation: The component requires further technical or invasive evaluation by qualified professional tradesman or service technician to determine the nature of any potential defect, the corrective action and any associated cost.

General

Property Type:	Single Family
Stories:	One
Approximate Age:	60 Years Old
Age Based On:	shelby County Assessors website
Bedrooms/Baths:	3/1.1
Door Faces:	North
Furnished:	No
Occupied:	No
Weather:	Overcast
Temperature:	Cool
Soil Condition:	Wet
Utilities On During Inspection:	Electric Service, Gas Service, Water Service

Square Footage



Comment 1:
measured square footage 1054 ft.²

Site

The condition of the vegetation, grading, surface drainage and retaining walls that are likely to adversely affect the building is inspected visually as well as adjacent walkways, patios and driveways.

Site Grading:	Mostly Level, Sloped Away From Structure Condition: Satisfactory
Vegetation:	Generally Maintained Condition: Satisfactory
Driveway:	Concrete Condition: Satisfactory
Walkways:	Concrete Condition: Satisfactory
Steps/Stoops:	Concrete Condition: Satisfactory

(Site continued)

Patios/Decks: Concrete
Condition: Satisfactory

Exterior

The visible condition of exterior coverings, trim and entrances are inspected with respect to their effect on the condition of the building.

Exterior Covering: Brick, Wood siding
Condition: Satisfactory

Exterior Trim Material: Wood
Condition: Satisfactory

Windows: Aluminum
Condition: Satisfactory

Entry Doors: Wood, Steel
Condition: Satisfactory

 Comment 2:
General pictures of exterior.



Figure 2-1



Figure 2-2

(Exterior continued)



Figure 2-3



Figure 2-4



Comment 3:

soffit and fascia damage at left front corner and right front corner of house as noted by pictures.



Figure 3-1



Figure 3-2

(Exterior continued)



Comment 4:
no doorbell installed at time of inspection.




Figure 4-1

Roofing

The visible condition of the roof covering, flashings, skylights, chimneys and roof penetrations are inspected. The purpose of the inspection is to determine general condition, NOT to determine life expectancy.

Inspection Method:	Walked Roof/Arms Length
Roof Design:	Gable
Roof Covering:	architectural shingles
	Condition: Satisfactory
Approximate Roof Age:	less Than Two Years Old
Ventilation Present:	Gable Ends, Ridge Vents
	Condition: Satisfactory
Soffit and Fascia:	Wood
	Condition: Satisfactory

Structure

The visible condition of the structural components is inspected. The determination of adequacy of structural components is beyond the scope of a home inspection.

Foundation Types:	monolithic slab
Foundation Material:	Poured Concrete
	Condition: Satisfactory
Floor Structure:	Concrete Slab
	Condition: Satisfactory
Wall Structure:	Wood Frame
	Condition: Satisfactory

Attic

Attic Entry:	Hallway
Roof Framing Type:	Joist and Rafters
	Condition: Satisfactory
Roof Deck Material:	Solid Wood Plank
	Condition: Satisfactory
Insulation:	Blown In Fiberglass, Blown In Cellulose
	Condition: Satisfactory

(Attic continued)



Comment 5:

Attic is in good condition.. Framing is sound and there is no evidence of leaks



Figure 5-1



Figure 5-2



Figure 5-3



Figure 5-4

Electrical

The inspector can not inspect hidden wiring or verify if the number of outlets is per the National Electric Code. A representative number of outlets, switches and fixtures are tested for operation.

Type of Service:	Overhead
Main Disconnect Location:	Service Panel
Service Panel Location:	Interior
Service Panel Manufacturer:	General Electric
	Condition: Satisfactory
Service Voltage:	240 volts
Service Amperage:	200 amps
Service Panel Ground:	Ground Rod
Branch Circuit Wiring:	Non-Metallic Shielded Copper
	Condition: Satisfactory
Overcurrent Protection:	Breakers
	Condition: Satisfactory
GFCI/AFCI Breakers:	Yes
	Condition: Further Evaluation Required
Smoke Detectors:	9 volt Battery Type
	Condition: Satisfactory

(Electrical continued)



Comment 6:



Figure 6-1



Comment 7:

carbon monoxide detector should be approximately light switch height.



Figure 7-1

(Electrical continued)



Comment 8:

Two electrical outlets, one outlet in hallway and hall bathroom and all electrical outlet outlets not working in second bedroom and master bedroom and GFI outlet not working in master bathroom Further evaluation needed by electrician, outlets in first bedroom,.



Figure 8-1



Figure 8-2



Figure 8-3



Figure 8-4

(Electrical continued)



Figure 8-5



Figure 8-6



Figure 8-7



Figure 8-8

(Electrical continued)



Figure 8-9



Figure 8-10



Figure 8-11

HVAC

HVAC System Type: Central Split System

Heating

The heating system is inspected visually and operated by normal controls to determine general condition NOT life expectancy. The capacity or adequacy of the heating system is beyond the scope of a home inspection. A licensed HVAC contractor should be consulted if in question.

Location:	Hallway
Type of Equipment:	Forced Air
	Condition: Satisfactory
Manufacturer:	Carrier
Heating Fuel:	Gas
	Condition: Satisfactory
Approximate Age:	14 Years Old
Filter Type:	Disposable
	Condition: Satisfactory
Type of Distribution:	Metal Ducting
	Condition: Satisfactory



Comment 9:
Heat operating as intended.
Register temps above 95 degrees

4225, Arrowhead, Memphis, Tn 38118



Figure 9-1



Figure 9-2

Furnaces over 10 years old should be checked, cleaned and serviced yearly by a licensed contractor.

Cooling

The cooling system is inspected by operation of the equipment by normal controls to determine general condition NOT life expectancy. The capacity or adequacy of cooling system is beyond the scope of a home inspection. A licensed HVAC contractor should be consulted if in question.

(Cooling continued)



Comment 10:
no AC condenser installed at time of inspection.



Figure 10-1

Air conditioners over 10 years old and heat pumps over 5 years old should be checked, cleaned and serviced yearly by a licensed contractor.

Plumbing

The plumbing system is inspected visually and by operating a representative number of fixtures and drains. Private water and waste systems are beyond the scope of a home inspection.

Supply Pipe Material:	Copper
	Condition: Satisfactory
Location of Main Water Shutoff:	At Meter
Waste Pipe Material:	PVC
	Condition: Satisfactory
Location of Fuel Shutoff:	At Meter

(Plumbing continued)

Water Heater

Manufacturer:	AO Smith
Fuel:	Natural Gas
Capacity:	40 gal
Approximate Age:	New Hot Water Heater
Fuel Disconnect:	In Same Room



Comment 11:

Hot water heater not operating at time of inspection.



Figure 11-1




Figure 11-2

Bathrooms

(Bathrooms continued)



Comment 12:



Figure 12-1



Figure 12-2




Figure 12-3

Kitchen

Cabinets:	Wood
	Condition: Satisfactory
Countertops:	Laminated
	Condition: Satisfactory
Sink:	Double
	Condition: Satisfactory



Comment 13:



Figure 13-1



Figure 13-2

(Kitchen continued)



Figure 13-3



Comment 14:
drawer in kitchen needs minor repair.



Figure 14-1

Laundry

Dryer Venting:	To Exterior
	Condition: Satisfactory
Laundry Hook Ups:	Yes
	Condition: Satisfactory



Comment 15:




Figure 15-1




Figure 15-2

Interior

The interior inspection is limited to readily accessible areas that are not concealed by furnishings or stored items. A representative number of windows and doors.

Floors:	Vinyl
	Condition: Satisfactory
Walls:	Painted Drywall
	Condition: Satisfactory
Window Types:	Single Hung
	Condition: Satisfactory
Window Materials:	Aluminum
Entry Door Types:	Hinged
	Condition: Satisfactory

(Interior continued)

Entry Door Materials: Wood, Steel
Interior Door Materials: Wood



Comment 16:
General pictures of Living room, dining area, bedrooms and closets.



Figure 16-1



Figure 16-2



Figure 16-3



Figure 16-4

(Interior continued)



Figure 16-5



Figure 16-6



Figure 16-7



Figure 16-8

(Interior continued)



Figure 16-9



Figure 16-10



Comment 17:
weatherstripping needed for front door.



Figure 17-1

(Interior continued)



Comment 18:
door leading to carport will not open.



Figure 18-1

Report Summary

Exterior

1) soffit and fascia damage at left front corner and right front corner of house as noted by pictures.



Figure 3-1



Figure 3-2

2) no doorbell installed at time of inspection.



Figure 4-1

(Report Summary continued)

Electrical

3) carbon monoxide detector should be approximately light switch height.



Figure 7-1

4) Two electrical outlets, one outlet in hallway and hall bathroom and all electrical outlet outlets not working in second bedroom and master bedroom and GFI outlet not working in master bathroom Further evaluation needed by electrician, outlets in first bedroom,.



Figure 8-1



Figure 8-2

(Report Summary continued)



Figure 8-3



Figure 8-4



Figure 8-5



Figure 8-6

(Report Summary continued)



Figure 8-7



Figure 8-8



Figure 8-9



Figure 8-10

(Report Summary continued)



Figure 8-11

HVAC: Cooling

5) no AC condenser installed at time of inspection.



Figure 10-1

(Report Summary continued)

Plumbing: Water Heater

6) Hot water heater not operating at time of inspection.



Figure 11-1




Figure 11-2

Kitchen

7) drawer in kitchen needs minor repair.



Figure 14-1

(Report Summary continued)

Interior

8) weatherstripping needed for front door.



Figure 17-1

9) door leading to carport will not open.




Figure 18-1